

Werkzeugliste Rechteck mit abgerundeten Ecken



Stand: 2010-12-06

Seite: 1

Breite:	Höhe:	Radius:
4,8	3	1,5
5	2	2
6	6	0
9	26	0
11	20	3
12	3	1
13,9	13,9	2
14	12	3
15	10	2,5
17	10	1
18	16	1
20	8	1,5
20	8	1,5
20	11	3
20	20	1
22,8	15,8	1,6
23	16	0
24	15	1,5
25	10	2
25	20	2,5
26	13	1
26,8	19,8	2
27	10	2
27	27	2
27,5	27,5	2
28	16	1
28	20	1
29,7	19,7	5
30	8	1
30	10	1,5
30	15	2
30	30	6
33	23	2
34	12	2
34	30	3
35	12	2
35	15	3
35	35	4
36	26	2
37	9	2
37	9	2
37	13	2,5

Breite:	Höhe:	Radius:
37	18	2
40	10	2
40	15	2
40	16	2
40	20	3
40	40	3
40	60	4
42	15	3
42,5	30	5
44	8	1
44	24	4
44	30	3
45	15	3
45	15	4
45	20	2
45	30	3
46	10	1,5
49,9	33,6	4
50	12	3
50	15	1,5
50	20	3
50	27	2,5
50	28	10
50	30	1
50	30	2
50	30	5
52	13	2
52	18	2
52	22	3
52	26	2,5
55	10	2
55	32	2
55	35	5,5
57,1	27,1	2
58	10	2
58,4	24,9	1,5
59,4	37,6	4
60	11	2
60	15	3
60	20	2
60	20	2
60	21	2

Werkzeugliste Rechteck mit abgerundeten Ecken



Stand: 2010-12-06

Seite: 2

Breite:	Höhe:	Radius:
60	25	2
60	25	2
60	25	3
60	30	2
60	32	3
60	40	4
61	16	1
64	12	1
65	25	2
65	25	2
65	25,1	3
65	30	2
65	30	2
65	30	3
65	50	3
68	54	5
70	16	3
70	20	2
70	25	2
70	30	2
70	30	2
70	30	3
70	35	5
72	12	2
72	30	5
73	15	2
74	36	4
74,4	21,4	3
75	20	3
75	30	3
75	34	3
75	35	4
75	38	3
75	40	2
75	40	4
75	40	4
75	45	5
76	28	3
78	44	0
78	48	3
80	16	1,5
80	20	2

Breite:	Höhe:	Radius:
80	24	3
80	25	3
80	25	8
80	28	5
80	30	3
80	55	3
80	55	3
80	65	3
85	25	3
85	54	2
85,5	54	3
90	50	3
96	12	2
100	45	5
100	50	11
100	50	11